5/29

DART AEROSPACE LTD	Work Order:	23635		
Description: STA 84 bracket	Part Number:	D2803-1		
Dwg: D2803 rev. A 20/10/10/20	Qty:	40 20		

Step	Location	Procedure	Ву,	Date	Qty	
1	EXPEDITING	Issue W/O	PA	05.06.21	10	20
2	METAL	Cut blanks per template DT8533 Material: 6061-T6 bar 10.00" x 0.50" Batch: Material: 6061-T6 bar 10.00" x 0.50"	强	05.06.76	ابح	20
3	HAAS	Machine as per folio FA102 Mas 18	130-	05.06.77	762	10
4	QC	Inspect Level 2	86	05.06.ZI	જ્	30
5	QC	Inspect Level 8	Ep	05/06/97		20
6	METAL ·	Tumble & Deburr	路	CS-06.71		70
7	QC	Inspect Level 5	En	oslubh		20
8	FINISHING	Chemical conversion coat per QSI 005		05,06.2		20
9	STORES	Identify and stock	m	05/08/05	20	RT
10	EXPEDITING	Close W/O Cost / part: 5 2.6 Suc os/08/05 (20)		05/08/05	20	
		53.27	*			•

Rev	Date	Change	Revised By A	proved
Α	00.11.06	New Issue	EC (/	١

RELEASED

Ec 00.11.06

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector			
05/08/03	9	Use 10 for B23625 and put the 10 others in Stores.	mil	02/08/02	10					
		·								

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Verification	Annroval	Approval	
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector	
		·							

Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA:	Date: <u>05/08/0</u>
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

DART AEROSPACE LTD	Work Order:	23635	
Description: Bracket	Part Number:	D2803-1	
Inspection Dwg: D2803 Rev: B		Page 1 of 1	


FIRST ARTICLE INSPECTION CHECKLIST


X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
12.625	+/-0.010	. 7.	neus	2 5 2	ut on Bu	ب د
Ø0.757	+0.005/-0.000	761		/\ /3.1	01 07 13	7.
Ø0.191	+0.005/-0.000	ાલા	~			
Ø0.507	+0.000/-0.001	.5067	<u></u>			
13.558	+/-0.010	13.558				
Ø0.507	+0.000/-0.001	-5062	~			
12.411	+/-0.010	12.411	/			
2.654	+0.000/-0.001	7.6535				
0.437	+0.000/-0.001	-4365				44-44
1.420	+/-0.001	1.420				
6.933	+/-0.010	6.933	~			
0.250	+/-0.010	. 754				
0.875	+0.000/-0.001	8741	~			
0.250	+0.000/-0.005	.748	2			
0.125	+/-0.010	.175	V			
0.125	+/-0.010	.130	V			
0.125	+/-0.010	1130	V			
0.125	+/-0.010	.176	V			
0.500	+/-0.010	1492	/			
0.562	+/-0.010	.554	~			
0.188	+/-0.010	.188				

Measured by: QC	Audited by:	Co	Prototype Approval:	N/A
Date: 05-06. 26	Date:	01/06/26	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	05.04.25	New Issue	KJ/JLM /	





Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Job Costing Report

Dart Aerospace Ltd Hawkesbury		Costing K		Jun 20 03:23 p	
Work Order No Project Name Project For Work Order Type Main WO Number House Part Number Description : ST Manufactured : Ye Amount Req'd :	TA 84 Bracket es 10		Department Co Burden Flags WO Status Invoice State Invoice Date Invoice Numbe Invoice Amoun	: NNNNNI : Open : Not In : er : at :	
Amount Done : Start Date Est Finish Date	0 : 06-20-05 : 07-23-05		Order Entry N OE Value	:	0.00
Act Finish Date Drawings Reqd	: : No		Est Mark Up Actual Mark U		000% 000%
Ok for Approval Approval Rec'd	: :		\$0 Posted to	Finished (Goods
=======================================	Estimated	Actual		Posted	To Post
Material Cost	: 0.00	0.00	0.00	0.00	0.00
Engineering Hours Engineering Cost Production Hours	: 0.00 : 0.00 : 0.00	0.00		0.00	0.00
Production Cost Packaging Hours	: 0.00	0.00	0.00	0.00	0.00
Packaging Cost OverHead Hours	: 0.00	0.00	0.00	0.00	0.00
OverHead Cost CNC Hours	: 0.00	0.00	0.00	0.00	0.00
CNC Misc. Hours	: 0.00	0.00	0.00	0.00	0.00
Misc. Hours	: 0.00	0.00	0.00	0.00	0.00
Burden	: 0.00	0.00	0.00		

0.00 0.00 0.00

Estimated

0.00

0.00

0.000

0.00

Actual

0.00

0.00

0.000

0.00

Total Cost

Mark up Selling Cost

Profits/(Loss)

Labour Hrs/Amount Done :